



CHANGES TO MSDS STATUS

DNA Extraction Control 670	BIO-35028	500 Reactions
DNA Extraction Control 670	BIO-35029	2000 Reactions

Dear User,

Due to following Directives the above mentioned products do not require a Material Safety Data Sheet (MSDS).

European Union Directives 67/548/EC and 1999/45/EC
OSHA 29CFR1910.1200
Commonwealth of Australia [NOHSC:1005,1008(1999)]

This is due to the product containing <1% of a hazard classified component or <0.1% of a carcinogenic classified component. For these reasons a MSDS has not been provided. Bioline Reagents Ltd. always recommend that when working with this or any other chemical suitable Personal Protective Equipment should be used, such as a laboratory coat, gloves and eye protection. Bioline Reagents Ltd. shall not be held liable for any damage resulting from the handling of or from contact with the above named product.

For further information please contact our Quality Assurance department at

Best regards,

Gentaaur Molecular Products
Voortstraat 49
1910 Kampenhout, BELGIUM

Tel 0032 16 58 90 45 | Fax 0032 16 50 90 45
www.gentaaur-worldwide.com
info@gentaur.com